

SL - 2.

Annex - 2

**FIBRE DUST COUNTING RESULTS AT WORK PLACES**

**ASSAM ROOFING LIMITED**

Bonda, Narengi

Guwahati, Assam

Sl. No.	Work Place	Maximum Exposure Limit (Indian Std.)	Dust Count Results (Fibre/cc)	
			Results (Oct, 2016)	Results (Jan, 2017)
1.	Fibre Godown	1	0.051	0.055
2.	Mill Area	1	0.069	0.064
3.	Fibre Treatment Area	1	0.053	0.057
4.	Sheet M/c Area	1	0.06	0.069
5.	QC Personnel	1	0.047	0.052
6.	Laboratory	1	0.05	0.04
7.	Moulding Filing Area	1	0.061	0.056
8.	Sheet Cutting & Filing Area	1	0.08	0.09
9.	Dry/Wet Waste Processing Area	1	0.052	0.057
10.	Scrap Asb. Sheet Stock Yard	1	0.033	0.038
11.	Emission from Fibre Dust Extractor	0.2	0.071	0.074

*Pankaj Baroi*  


Checked By: Pankaj Baroi, ENVIROCON

**NOTE:**

1. Results reported are valid at the time of and under the prevailing conditions of measurement.
2. Results refer only to the particular parameters tested.
3. This test report shall not be reproduced except in full, without the written permission of ENVIROCON, Digboi Stores Building, New Market, Digboi - 786171, Assam.

**Core Services:** Environmental Monitoring & Data Generation, EIA & EMP, Environmental Audit & Allied Environmental Management jobs  
**Associate Services:** Certification by Competent Person (CIF), NDT, Hydraulic Testing, Chartered Engineer Services etc.