

Report No.: ENV/ARL(ABS)/GHY/21-22/N-09/01
Date : 27/09/2021

Order No.:
Date :

Report Issued To : **ASSAM ROOFING LIMITED (Asbestos Unit)**
Bonda, Narengi, Guwahati – 26 (Assam)

NOISE LEVEL MEASUREMENT RESULTS

Date of Measurement: **08.09.2021 (Day Time)**

Sl. No.	Locations	Maximum (dB-A)	Minimum (dB-A)	L _{eq} (dB-A)
1	Main Machine Area*	81.7	79.8	81.2
2	Near Corrugators*	81.3	80.2	80.8
3	Mill Area	74.6	72.6	73.5
4	Fiber Treatment Area	75.3	72.9	74.1
5	Stripping Area*	79.5	77.6	78.4
6	Mechanical Workshop	74.2	72.3	72.9
7	Near Plain Sheet Godown	67.8	64.3	66.2
8	Wet Ball Mill Area*	89.8	87.7	88.6
9	Near Main Gate	61.8	49.6	54.6
10	Near Administrative Building	62.4	51.8	56.7

Limit: Day Time- 75 dB(A)

***Remarks:** PPE (Ear Plugs) is recommended in the above locations.



Checked By: Mr. Pankaj Baroi, **ENVIROCON**

- NOTE:**
1. Results reported are valid at the time of and under the prevailing conditions of measurement.
 2. Results refer only to the particular parameters tested.
 3. This test report shall not be reproduced except in full, without the written permission of ENVIROCON, I.O.C.L (AOD) New Market, Digboi – 786171, Assam.

Core Services: Environmental Monitoring & Data Generation, EIA & EMP, Environmental Audit & Allied Environmental Management jobs
Associate Services: Certification by Competent Person (CIF), NDT, Hydraulic Testing, Chartered Engineer Services etc.

Assam Roofing Limited

Noise Monitoring Data (Noise Level 8 Hourly db)

Sl no.	Locations / Area	Apr-21	May-21	Jun-21	Jul-21	Aug-21	Sept-21
1	Main Machine Area	86.9	81.2	83.2	82.1	82.3	83.4
2	Near Corrugator	81.4	82.7	82.1	81.5	82.7	83.4
3	Mill Area	82.8	80.3	80.2	81.1	78.9	76.8
4	Fibre Treatment Area	78.9	69.8	75.1	76.9	75.5	77.3
5	Stripping Area	73.6	72.6	70.6	70.4	77.5	77.7
6	Mechanical Workshop	82.4	82.1	81.9	82.9	82.1	82.4
7	Near Plain Sheet Godown	72.2	72.6	75.2	73.2	70.4	70.4
8	Wet Ball Mill Area	90.2	91.4	91.4	90.4	93.6	92.6
9	Near Main Gate	64.8	64.2	68.2	68.4	68.2	67.8
10	Near Administrative Building	62.4	61.8	57.6	63.2	64.2	63.2

Remark : Location like Ball mill area, DG ares, Main Machine area, Near Corrugator - work men provide Ear Plug